

Service	£225
Split & Reseal	£30
Battery Connectors	£15
Main Wiring Loom	£35
Internal Fuse	£6
LED (each)	£8
LED Loom	£34
Charging Socket	£14
Power LED	£15
Aerial Socket	£15
On/Off Button	£45
Handle Assembly	£30
Motors/Pumps	£64
Main Printed Circuit Board	£35
Main Printed Circuit Board HD	£85
Main Printed Circuit Board Box	£15
Futaba T6L 40mHz Handset	£250
Futaba T6L 2,4Ghz Handset	£180
Flexinol Wire	£42
Hopper Servo (each)	£49
Door Rubber Seals & Catches	£14
Body Work Rear Stiffner	£15
Check Radio Range (lake test)	£25
Check Radio Range (on ste)	£15
Weed Guards	£40
Battery Boxes L or R	£40
Spotlight Assembly	£35
Hopper Door	£21
Line Guide	£15
Replace Handset Joystick	£50